

Maker	Vehicle Name	Model	Front Door	Rear Door	Remarks
Suzuki	Alto works	HA36S	OK	OK	Four TOYOTA genuine bolts (90148-80066-A) with threadlocker (such as LOCTITE TB2468) are required.
	Ignis	FF21S	OK	OK	
	Xbee	MN71S	OK	OK	
	Jimny	JB23, JB64W	OK	N/A	
	Swift	ZC83S	OK	OK	
	Swift Sports	ZC33S	OK	OK	
	Hustler	MR31S	OK	OK	
	Rapin	HE33S	OK	OK	
	WagonR	MH55S	OK	OK	
Mazda	Flair	MJ55S	OK	OK	
Subaru	BRZ	ZC6	OK	N/A	Four TOYOTA genuine bolts (90148-80066-A) are required.
Toyota	86	ZN6	OK	N/A	
	iQ	NGJ10, KGJ10	OK	N/A	
	Aqua	NHP10	OK	OK	
	ALTEZZA	SXE10, GXE10	OK	OK	
	WISH	ZGE25W	OK	OK	
	Vitz (130 series)	KSP130, NCP131, NSP13#	OK	OK	
	Vitz (90 series)	SCP90, NCP91, NCP95, KSP90	OK	OK	
	Vitz (10 series)	SCP10, NCP1#	OK	OK	
	MR2 (20 series)	SW20	OK	N/A	
	FJ Cruiser	GSJ15W	OK	N/A	
	Auris (180 series)	ZRE186H, NZE181H	OK	OK	
	Corolla Fielder (160 series)	ZRE162G, NZE161G	OK	OK	
	Corolla Levin (80 series)	AE86	OK	N/A	Four TOYOTA genuine bolts (90148-80066) are required.
	Crown Athlete/Royal (210 series)	GRS21#, AWS21#	OK	OK	
	Crown Athlete/Royal (200 series)	GRS20#	OK	OK	
	Crown Majesta	GWS214	OK	OK	
	Crown	AZSH20	OK	OK	
	SAI	AZK10	OK	OK	
	Sprinter Trueno (80 series)	AE86	OK	N/A	Four TOYOTA genuine bolts (90148-80066) are required.
	Celica (230 series)	ZZT23#	OK	N/A	
	Tundra	USK56L	OK	OK	
	Hilux	GUN125	OK	OK	
	Harrier (60 series)	ZSU6#W, AVU65W	OK	OK	
	Harrier (30 series)	ACU30W, ACU35W	OK	OK	
	Prius/PriusPHV (30 series)	ZVW30, ZVW35	OK	OK	
	Prius alpha	ZVW4#	OK	OK	
	Mark X (130 series)	GRX13#	OK	OK	
	Mark II (110 series)	JZX110, GX110	OK	OK	
	LAND CRUISER PRADO	GDJ150W	OK	OK	
	RAV4	ACA36W, ACA31W	OK	OK	
VIOS	NSP151L	OK	OK		
FOURTUNER	GUN156R	OK	OK		

Warning

Do not install on unsuitable models.

When installed to unsuitable models, the door may not close completely and be damaged.

Furthermore, accidents can occur if the door opens while the vehicle is on the move.